09-18-06

10/815364

CefC



"Express Mail" mailing label number:

EV 517995659 US

Date of Deposit:

September 15, 2006

Type of Document(s):

Request for Certificate of Correction of

Patent For PTO Mistake (37 C.F.R.

§1.322(a));

Certificate of Correction (PTO/SB/44)

(In Duplicate); and Return Postcard

U.S. Patent No.:

6,996,877

Date Issued:

February 14, 2006

I hereby certify that the documents identified above are being deposited with the United States Postal Service "Express Mail Post Office to Addressee" service under 37 C.F.R. §1.10 on the date indicated above and are addressed to the Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Catherine A. Johnson

Certificate of Correction

SEP 20 2000

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number:

6,996,877

Issued:

February 14, 2006

Name of Patentee:

Booker, et al.

Title of Invention:

SNAP-ON HINGE ASSEMBLY

Attention Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 C.F.R. § 1.322(a))

- 1. Attached, in duplicate, is Form PTO/SB/44, stating the text of the correction. At least one copy is suitable for printing.
 - 2. The line numbers where the errors are shown in the patent is:
 - (a) Column 9, line 27
 - (b) Column 12, line 35

The correction requested above, as stated in Form PTO/SB/44, involves no new matter.

- 3. The error appears to be a printing error.
- 4. Because this is a request for a certificate of correction of a Patent Office mistake, no fees are believed due.
 - 5. Please send the Certificate of Correction to:

Name:

John M. Harrington, Esq.

Address:

Kilpatrick Stockton LLP

1001 West Fourth Street Winston-Salem, NC 27101.

Date: 9/15/06

John M. Harrington

Kilpatrick Stockton LLP 1001 West Fourth Street Winston-Salem, NC 27101

Reg. No. 25,592

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

CERTIFICATE OF CORRECTION

PATENT NO: 6,996,877

Page <u>1</u> of <u>1</u>

APPLICATION NO.: 10/815,364
ISSUE DATE: February 14, 2006

INVENTOR(S): Todd Booker, Georg Domenig

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 9, line 27, that portion reading "110. Near the back end of the frame plate 10," should read -- 110. Near the back end of the fram plate 110 --.

Column 12, line 35, that portion reading "a an intermediate plate comprising a body portion" should read -- an intermediate plate comprising a body portion --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

John M. Harrington
1001 West Fourth Street
Winston-Salem, NC 27101

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

PTO/SB/44 (04-05)
Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,996,877

Page <u>1</u> of <u>1</u>

APPLICATION NO.: 10/815,364
ISSUE DATE: February 14, 2006

INVENTOR(S): Todd Booker, Georg Domenig

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 9, line 27, that portion reading "110. Near the back end of the frame plate 10," should read -- 110. Near the back end of the fram plate 110 --.

Column 12, line 35, that portion reading "a an intermediate plate comprising a body portion" should read -- an intermediate plate comprising a body portion --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

John M. Harrington

1001 West Fourth Street

Winston-Salem, NC 27101

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.